Form IV (See Rule 13) ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier health care facility(HCF), or common bio-medical waste treatment facility (CBWTF)]

Return No:

59120968

Period: 2023-2024

1. Particulars of the Occupier				
(i) Name of the authorized person (Occupier or operator of facility):	Dr PADMAJA GIREESH			
(ii) Name of HCF or CBMWTF:	PADMA CLINIC AND NURSING HOME.			
(iii) Address for Correspondence:				
(iv) Address of Facility:	752 & 753, Poonamallee High Road, Kilpauk, Chenna			
(v) Tel. No.:	752 & 753, Poonamallee High Road, Kilpauk, Chennai 9551762734			
(vi) Fax. No.:	044 - 26426766			
(vii) E-mail ID:				
(viii) URL of Website:	padmaclinic2010@gmail.com			
(ix) GPS coordinates of HCF of CBMWTF:	13 081206 N 90 259067 F			
(x) Ownership of HCF or CBMWTF:	13.081296 N, 80.258967 E Private			
(xi) Status of Authorization under the BMW (Managementand Handing) Rules:	Authorization No.: 22BAD44401178 Valid Upto: 31/03/2024			
(xii) Status of Consents under Water Act and Air Act.:	Valid Upto: 31/03/2024			
2. Type of Health Care Facility	7 and Opto. 31/03/2024			
HCF/CBMWTF Type:	HCF			
i) No. of Beds(for Bedded Hospital):	40.0			
ii) Non-Redded Hospital	NOT APPLICABLE			
ii) Licence Number:	0			
v) Licence date of expiry:				
	Yellow Category: 3228.09 Red Category: 2987.6 White Category: 56.2 Blue Category: 336.3 General Solid Waste: 3150			
Details of the Storage, Treatment, Transportation, Processing	ng and Disposal Facility Details			
so the on-site storage facility:	Size: 3 Capacity: 50 Provision of on-site storage: CLOSED SHED AREA			

(ii) Disposal Facility:		Type of Treatmen t Equipmen t	Number of Units	Capacity(Kg/day) 2 BIN CAPACIT Y	Quantity Treated or Disposed(Kg/annu m)		
		Autoclaves				,	
	Needle tip cutter or destroyer Chemical Disinfectio n	2	0 1-5 LPH	0			
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	0.0						
(iv) No of vehicles used for collection and transportation of BMW:	0						
(v) Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum		Type of was		ntity rated	Where disposal		
			List is	Empty			
(vi) Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	G.J. Multiclave (India) Pvt Ltd						
5. Do you have BMW management committee:	no						
6. Training Conducted on BMW Details							
(i) Number of training conducted on BMW Management:	2						
(ii) Number of personnel trained:	20						
(iii) Number of personnel trained at the time of induction:	15						
(iv) Number of personnel not undergone any training so far:	0						
(v) Whether standard manual for training is available:	yes						
(vi) Any other information:	NILL						
7. Details of the accident occurred							
(i) No. of accident occurred:	0						
(ii) Number of the persons affected:	0						
(iii) Remedial Action taken:	0					7	
(iv) Any Fatality occurred, details:	0						
8. Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	NOT APPLICABLE						
Details of Continuous online emission monitoring systems installed:	NOT APPLICABLE						
9. Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	TREATED WITH SODIUM HYPO DOSING SYSTEM						
0. Is the disinfection method or sterilization meeting the og for standards? How many times you have not met the tandards in a year?:	TREATED WITH SODIUM HYPO DOSING SYSTEM						
1. Any other relevant information:	NILL	N-19/					

Name and Signature of the Head of the Institution

Date : 15/04/2024
Place : Chennai